

NPIF Richmond Hill Victoria Street Link 6 th July 2020 update	Photograph no.	Comments / observations or issue
	07-07-2020	Road markings being placed at BCW junction with Ainsworth st
	07-07-2020	Road markings being removed exchange st
	07-07-2020	Surfacing to BCW slip rd into Ainsworth st Showing new surfacing laid approx. 5mm higher than dropped kerb DLO have been notified .