




NPIF progress – week commencing 2 <sup>nd</sup> December 2019	Photograph no.	Comments / observations or issue
	03-12-2019	Attenuation drainage at manhole position Richmond terrace.
	03-12-2019	Traffic signal ducting being placed in excavation at Richmond terrace.
	04-12-2019	Drag box now in position but needs moving to align with 3x300mm drains placed earlier



06/12/2019

Sheet Piling for Manhole excavation.



06/12/2019

Excess water being pumped out of excavation.