


NPIF Northgate / Victoria Street Link Road weekly update	Photograph no.	Comments / observations or issue
	02-07-2020	Advanced warnings in place for last 2 weeks
	02-07-2020	Narrow widening following junction change BCW
	02-07-2020	As above at Victoria st junction

	04-07-2020	Milling out 45mm of existing surfacing junction BCW and ainsworth st
	04-07-2020	Binder laid to narrow widening BCW
	05-07-2020	Ultipave being laid @ BCW

 A worker in a high-visibility vest is operating a road marking machine on a street. The machine is applying white lines to the asphalt. The street is lined with orange traffic cones and green safety barriers. In the background, there are buildings, including one with a sign that says 'CAPITA SUPPLIES'.	05-07-2020	Roadmarkings commenced
 A tackcoat machine is applying a dark coating to a road surface. The machine is a large truck with a tank and a spreading mechanism. The road is lined with orange traffic cones and green safety barriers. In the background, there are buildings and a yellow excavator.	05-07-2020	Tackcoat machine laid